

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

SEENA KUMARY D  
St John's School, Thumpamon  
Thumpamon, Pandalam

GR 1078.00 m<sup>2</sup>  
FF 971.00 m<sup>2</sup>  
SF 971.00 m<sup>2</sup>  
Rear bldg 901.00 m<sup>2</sup>  
Total 3921.00 m<sup>2</sup>

5. Period for which the certificate is issued

2023 - 24

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

nd

7. Any major defects noticed which will render the building unsafe in any manner

No

8. Whether maintenance works have been done properly

Yes.

9. Whether the structure is sound or not for conducting classes

Yes. The buildings are sound under normal wind and weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


## CERTIFICATE


certified that the school building was inspected by me on 23/6/2023 and found to be fit / ~~unfit~~ to conduct classes, for the period 2023 - 24 for the reasons stated above.

Place: Thumpamon  
Date: 23/6/2023



  
ASSISTANT ENGINEER  
LSGD (LID & EW) SECTION  
THUMPAMON G.P.  
Assistant Engineer

For St. John's School  
  
Manager

  
D. SUSAN GEORGE  
PRINCIPAL  
ST. JOHN'S SCHOOL  
KEERUKUZHAY, P.O.  
THUMPAMON  
KERALA

